

# Safety regulations 2020



## Safety

- Safety distance when driving must be so large that no-one can get injured during the driving. The driver of the vehicle is fully responsible.
- Stand items must be set up securely
- We will be employing health & safety consultant to visit all stands on Monday 22<sup>nd</sup> of June and Tuesday 23<sup>rd</sup> of June. They will also be in attendance during the whole first show day, 24<sup>th</sup> of June, and during the afternoon of the last show day, 25<sup>th</sup> of June.
- We will be emphasising parental responsibility in the show catalogue. Parents are responsible for the children at all time during the exhibition.
- First aid material will be available in the Information marquee at the main entrance
- First aid professionals will be in attendance on-site
- First Aid staff will walk around the showgrounds and can be reached from the Information tent at the main entrance, or by any of Borgeby Fältdagars Crew-members.
- Packing up the stands can start from 17:00 on 25 June. Outward transport by vehicle from the show area is not permitted before 18:00 due to visitors' safety!

## Basic requirements according to Swedish Work Environment Act 3, Ch. 8 §

"Any person manufacturing, importing, delivering or providing a machine, implement, protective equipment or other technical device shall ensure that the device affords adequate security against ill-health and accidents when it is placed on the market, delivered to be used or displayed for sale. A technical device not meeting the requirements of subsection one may be shown at trade fairs, exhibitions or suchlike if it is made clear that the requirements are not satisfied and that the device may not be placed on the market or delivered to be used until it meets the requirements. If the device is set in operation, adequate safety precautions shall be taken for the prevention of accidents.

Information on the device which is of significance to prevent ill-health and accidents (product information) shall be enclosed upon delivery through clear marking or in some other manner. Information of particular significance for the work environment shall be submitted in the event of marketing of the devices." (Paragraph amended by SFS 1992:1135)

## SAFETY REGULATIONS

When a tractor or machine has a mechanism in the raised position, it must be ensured that this mechanism cannot change position in a way that causes damage to person. Hydraulic pistons etc. must be mechanically locked.

Machines, tractor tyres etc. must be fixed in place to prevent the risk of rolling.

Exhibitors must ensure that show visitors are shielded from sharp edges or pointed objects. Explosive goods and other products deemed unsuitable from a safety perspective by Borgeby Fältdagars may not be displayed.

Before the use of pressurised vessels during the show, the exhibitor must obtain specific permission from Borgeby Fältdagars. Any goods displayed must conform with the statutory regulations imposed by state authorities and inspectorates and, if required, approval must be obtained from these

persons. Exhibitors are reminded of their obligations under the Swedish Work Environment Act as regards the display of machines etc.

Borgeby Fältdagar absolves itself from all responsibility for damage or consequences arising from non-compliance with the regulations and for failure to obtain the necessary permissions. Exhibitors are liable to compensate Borgeby Fältdagar for all charges or damages arising thereby.

Demonstrations of machines with a high volume of noise or machines that can cause damage to person may only be carried out within the demonstration sites specified by Borgeby Fältdagar and with a clearly demarcated safety zone between machines and show visitors. Those wishing to carry out demonstrations at their stand must observe the safety distance to the public and ask for a special permission from Borgeby Fältdagar

## **During unloading and loading at the stand or in the show area, the safety distances must always be observed:**

During unloading/loading, the safety distance for persons must be double the distance between the working parts of the loader machine and the distance of the raised material above the ground. For example, when using a loader with a lifting height of 5 metres above the ground to lift material, the safety distance is 10 metres from the lift area of the loader (the lift area is the area of the loader where the material is raised/suspended).

When unloading/loading using a crane with a lifting height of up to 10 metres above the soil, the safety distance is 20 metres from the lift area of the machine (the lift area is the area of the crane where the material is raised/suspended).

If necessary, and in the case of special safety risks with show material with large dimensions or high weight, the exhibitor must employ personal safety guards or contact Borgeby Fältdagar beforehand.

## **General rules on driving within the showgrounds**

Vehicles that have to be moved within the show area during opening hours must observe the obligation to give way and a speed limit of **max 10 km/hour**.

Traffic in the show area is one-way, as indicated on the show map.

Terrain vehicles or open four-wheel drive vehicles must observe the obligation to give way and a speed limit of max 10 km/hour and, in addition, drivers of these vehicles must wear a safety helmet if there is no rollbar fitted.

During demonstrations with working machines, a safe distance to persons on the ground must be maintained. This is generally 10 metres as a minimum distance, while for machines with a risk of throwing up stones, e.g. forage harvesters, it must be at least 20 metres.

Exhibitors wishing to re-stock or move show material must observe the safety of show visitors and exhibition staff.

By booking a stand at Borgeby Fältdagar you accept the Safety Regulations for Borgeby Fältdagar 2020. Likewise, you accept the "General Terms and Conditions for Exhibitors at Borgeby Fältdagar 2020" Both documents can be found on the webpage and you will be directed to them by a link in your booking confirmation.